

Towards improved Quality of Works



Heike Erhorn-Kluttig, Hans Erhorn, Fraunhofer Institute for Building Physics

Workshop “Voluntary and Regulatory Frameworks to Improve Quality and Compliance”

Lund, 16 March 2015



© Fraunhofer IBP

Quality of Works within QUALICheck



Tasks:

- Examples of existing situations regarding the quality of works
- Analysis of the reasons for good and poor quality of works
- Set of possible approaches ('best practices') for improved quality of works

Approach:

- 3 reports based on the tasks
- Factsheets on interesting approaches
- Working together with other focus areas within QUALICheck: data collection from participating countries, better compliance and effective penalties
- Market feedback: stakeholders, QUALICheck platform, events, webinars, road shows, BUILD UP Skills

© Fraunhofer IBP

Critical Situations on the Construction Site



QUALICHeCK focus area			Transmission characteristics		Ventilation			Sustainable summer comfort technologies	Renewables in multi-energy systems	
			Whole component	Thermal bridges	Airtightness of envelope	Airtightness of ducts	Systems			
Critical situation										
Building envelope	Opaque	Components to ground	Wrong (insulation) material: water resistance	E2 / S1 / RI						
		Base slab/foundations	Wrong (insulation) material: pressure resistance	E2 / RI						
		Ventilated roof	Not enough air space for ventilated roof							
	Transparent	Cool roof	Wrong coating for cool roof					US-GI		
			Wrong windows or façade elements: U-value	D1 / RI				D1		
		General	Wrong windows or façade elements: g-value, τ-value	D1 / RI					D1	
			Joints between windows and walls not insulated		D1 / E2 / DI / DIH / EI / RI					
			Joints between windows and walls not watertight/airtight	D1 / E2 / S1 / RI	D1 / S1 / DI / DIH / EI / RI	D1 / S1 / EI / RI				
		Shading systems	Top mounted roller shutters uninsulated at contact surface to wall		D1					
			Blinds without sufficient rear-ventilation							

Critical Situations on the Construction Site



QUALICHeCK focus area			Transmission characteristics		Ventilation			Sustainable summer comfort technologies	Renewables in multi-energy systems
			Whole component	Thermal bridges	Airtightness of envelope	Airtightness of ducts	Systems		
Critical situation									
Building service systems	General	Wrong system components installed: collector peak load, inverter efficiency, fan efficiency, pump efficiency, etc.							
		Incorrect setting of hydraulic flows						A1, S1, EU2	
		No hydraulic calibration							
	Fixation	Incompatible mounting material: anchors, etc.							
		Wrong diameters of pipes/ducts							
	Pipes/ ducts	No/poor insulation of pipes/ducts							
		No accessibility for cleaning							
		Duct connections not airtight				EU1 / SH			
	Control	Joints with other system components not airtight: fan, AHU				EU1 / SH			
		Wrong settings: night setback, CO ₂ /humidity/temperature controls							A1, EU2
	PV system	Damaged PV cells							
		Not enough rear ventilation							
		Cables: Mistakes regarding parallel vs. series connection							
No connection to inverter									
Insulation behind the arrays not high temp.resistant									
	Incorrect installation on the roof, causing water leakage								
	Incorrect installation on the roof, causing damages on								

Critical Situations on the Construction Site



QUALICHeCK focus area		Transmission characteristics		Ventilation			Sustainable summer comfort technologies	Renewables in multi-energy systems
		Whole component	Thermal bridges	Airtightness of envelope	Airtightness of ducts	Systems		
Building service systems	Solar thermal	Not enough distance/insulation behind collectors at walls/roofs						
		Insulation behind the panels not high temperature resistant (e.g. integrated in facades)						
		Storage feed-in at middle/top						EU2
	Heat pump	Setting: no priority for DHW						
		Storage feed-in at top (DHW) and middle (heating)						
		Too low refrigerant quantity						F1
		Incorrect positioning of the outdoor unit (too close to walls, in an attic) -> poor performance						F1
	Ventilation system	Time for defrosting of the outdoor heat exchanger set at a too low value -> poor performance						F1
		Setting of airflow rate on default instead of specific necessary setting/wrong air flow rates						
		Required filters not included					A2	
No electrical connection of the auxiliary heating						F1		
	Installation without accessibility for maintenance					A2		

© Fraunhofer IBP

Documented Examples of existing Situations regarding Quality of the Works



© Fraunhofer IBP

Reasons for poor quality:

1. **Poor specifications** at level of projects, standards, regulations:
 - a. Materials to be used (e.g. material characteristics of insulation, correct construction details (joints), ...)
 - b. Performances to be achieved (e.g. air- and watertightness, wind resistance for PV panels, acoustical performances of ventilation systems, ...)
 - c. With respect to the execution principle (e.g. under which conditions may roofing be installed)
2. **Lack of competence**
 - a. Designer level (see also QUALICheck work package "Reliable and easily accessible input data")
 - b. Execution level
 - c. Language barriers
3. **Critical economic conditions**
 - a. Critical financial conditions
 - b. Critical timing conditions
4. **Lack of control**
 - a. By parties involved in the project
 - b. By third parties (government, independent control organisations, ...)

Documented Examples of existing Situations regarding Quality of the Works



Study	Country	Reported by	Covered areas	Date of study	Transferability	Results/consequences
Field test on combined heat pump and solar thermal systems	Austria	OEGNB	Heat pumps, solar thermal systems	2010-2013	National, international	Revised training material for installers
Study on ventilation systems in classrooms	Austria	OEGNB	Mechanical ventilation systems in classrooms	2008	National, international	Revised training material for ventilation installers
Impact of storm on PV systems	Belgium	BBRI	Installation of PV systems	2010-2013	National, international	Development of design and installation specifications
Cypriot analysis of the National Status Quo within BUILD UP Skills	Cyprus	The Cyprus Institute	Insufficient knowledge/training, necessary specialists not part of construction team	2012	National, international	Roadmap for policies and actions for construction sector employees
Burgholzhof study	Germany	Fraunhofer IBP	Insulation material, quality of windows, thermal bridges, window seams, roller shutters	2002	National, international	General: U-value definitions of glazings have been revised; practical recommendations
Estonian analysis of the National Status Quo within Build Up Skills	Estonia	Tallinn University of Technology	Insufficient knowledge of new technologies/construction workers not adequately trained	2012	National	The number of skilled workforce needs to be increased
Estonian housing stock technical condition - apartment buildings (1990-2010)	Estonia	Tallinn University of Technology	Insulation material, damages on construction site, wet insulation, waterproof layers, built-in moisture, moisture and air barriers, joints	2010-2012	National, countries with similar constructions & climate, partly international	Guidelines for designers and builders
Quality of ventilation systems in residential buildings: status and perspectives in Estonia	Estonia	Tallinn University of Technology	Ventilation systems: Joints not airtight, no accessibility for cleaning/ maintenance, wrong settings, filters not included	2013	National, partly international	Guidelines for HVAC designers and builders
EU project SAVE DUCT	EU (focus on BE, F, S)	BBRI	Ductwork, airtightness	1997-1998	International	Recommendations to use circular ducts and factory-fitted sealing gaskets


17 documented Examples of existing Situations regarding Quality of the Works



Study	Country	Reported by	Covered areas	Date of study	Transferability	Results/consequences
EU project CombiSol	EU (focus on A, F, D, S)	OEGNB	Installation of solar thermal systems	2007-2010	International. Test included systems from 4 countries	Guidelines for manufacturers and installers
Study on common problems with heat pumps	France	Cetiat	Heat pumps	2009	National only	Advice to join the quality label QualiPac
Romanian analysis of the National Status Quo within Build Up Skills	Romania	URBAN-INCERC	Time pressure, insufficient knowledge/training, necessary specialists not part of the construction team	2012	National	Starting point for the definition of a national qualification strategy and a roadmap
Småhuss-kadenämnden (The board for moisture and mould damages in single-family house)	Sweden	Chalmers University of Technology	Time pressure, insufficient knowledge/training, insulation material, construction damages, wet material, waterproof layer, water resistance, hydraulic flows	2001	National, countries with similar constructions & climate, partly international	Education and information reg. less risky construction types. Foundations with insulation above concrete slabs are no longer used.
Wrong insulation material in loose fill insulations in attics	Sweden	Chalmers University of Technology	Wrong insulation material; λ -value, thickness, etc.	1998	International	Practical recommendations for improvement
Problems with external thermal insulation composite systems (ETICS)	Sweden	Chalmers University of Technology	Joints not watertight/airtight	2009	National, countries with similar constructions & climate	Recommendations for safe ETICS constructions in the Swedish situation
The causes and costs of defects in construction	Sweden	Chalmers University of Technology	General, especially lack of motivation/ control	1999	Probably international	45 % of the detected defects originated from the construction site, mostly by lack of motivation
Factors that affect the building's air tightness	Sweden	Chalmers University of Technology	Building airtightness	2010	National, countries with similar constructions	Recommendations for improved building airtightness (0.3 l/sm ²)

Example: Burgholzhof: Surveillance of Design and Construction Work



- 500 residential units in low energy level
 - Fraunhofer IBP contracted by city of Stuttgart check EP calculations, design of joints, realisation on site
- 
- to
- Quality check for all three parts was important:
 - Proofs of thermal protection had to be corrected, up to 4 times
 - Many of the details had to be improved/clarified by adding material descriptions, etc.
 - Windows U-values and g-values did not meet specifications (at that time two types of U-values: measured acc. DIN and officially published with „safety“ allowances, g-values deemed less important)
 - Thermal separation of balcony plates not accurate, filled partly with mortar or concrete (thermal bridges)
 - Window seams filled with polyurethane foam (not durable elastic)
 - Insulation material with inferior thermal conductivity
 - Top mounted roller shutters create thermal bridges at the location where the shutters are on top of the wall
 - Additional insulation on the inner side of cellar walls problematic (pipes, fixtures)

15 Best Practice Examples to solve the critical Situations



Solution	Country	Reported by	Covered areas	Date of solution	Type of solution	Legal/ other	Transferrability
Training and certification schemes for installers at AIT	Austria	OEGNB	Installation of heat pumps, PV, solar thermal and ventilation systems	Since 2001	Training and certification of installers	Voluntary, recommended by klimaaktiv	Yes
Guidelines, checklists and commissioning protocols by professional associations	Austria	OEGNB	Installation of heat pumps, PV, solar thermal and ventilation systems	Since ca. 2005	Guideline, checklist, Comm. protocol	Voluntary	Yes
Voluntary building certification including measurements	Austria	OEGNB	Building envelope quality	Pilot phase in 2001, in place since 2003	Quality assessment by third party	Voluntary	Yes
IEE project WE-Qualify	Cyprus	The Cyprus Institute	Knowledge/training, specialisation, material, installation, damages during construction, wet material, roller shutters	2013 + 36 months	Education of workers (training material + training)	Recommendative/ voluntary	In general yes
Scheme of Vocational Qualifications: I have the qualifications. I certify!	Cyprus	The Cyprus Institute	Knowledge/training, specialisation	2013, ongoing	Education and certification of workers	Recommendative/ voluntary	In general yes
RAL Window and Front Door Installation Guideline	Germany	Fraunhofer IBP	Window installation, airtightness, water tightness, thermal bridges at window/wall connection	Since 1998, regular updates	Guideline and education of workers	Accepted rules of technology	Yes
RAL Certification of Window Installation	Germany	Fraunhofer IBP	Window installation, airtightness, water tightness, thermal bridges at window/wall connection	Since 1998	Certification of manufacturer including installation	Voluntary	Yes

15 Best Practice Examples to solve the critical Situations



Solution	Country	Reported by	Covered areas	Date of solution	Type of solution	Legal/ other	Transferability
Guidelines for dwelling designers, builders, owners	Estonia	Tallinn University of Technology	Technical details, insulation layers, airtightness material, joints	2010-2012	Guideline	Voluntary	Yes
BUILD UP Skills QualiShell project	Romania	URBAN-INCERC	Knowledge/training, qualification of workers, building envelope: transmission charact. + envelope airtightness	2013-2015	Qualification schemes, mechanism for long lasting large scale implementation	Integrated in the national qualification system	Partially
Swedish guidelines on waterproof layers in wet areas (GVK, BBV)	Sweden	Chalmers University of Technology	Waterproof layers in wet areas	Since 1988	Education of workers, guidelines and authorisation of companies	Voluntary, several insurance comp. require work acc. GVK/BBV	Yes. Negotiations with insurance companies
Quality framework for ducts	Sweden	Chalmers University of Technology	Air duct tightness	Since 1966	Airtightness test and certification	Voluntary, but applied in 90-95% of buildings	Yes
Guideline BuilDE - Energy efficient	Sweden	Chalmers University of Technology	Communication between planners and contractors	Initiated in 2013	Checklist, guidelines, standardisation of calculation tools	Voluntary	Probably yes
Quality framework CIGA for insulation of cavity walls	UK	Fraunhofer IBP	Cavity wall insulation	Since 1995	Certificate for installers, guarantee for home owners	Voluntary	In general yes. Connection to UK ministries
Quality framework SWIGA for insulation of solid walls	UK	Fraunhofer IBP	Solid wall insulation	2010	Certificate for installers, guarantee for home owners	Voluntary	In general yes. Connection to UK ministries
Guideline for selecting cool roofs	US/ Greece	University of Athens	Cool roofs	2010	Guideline	Voluntary	Countries/regions with hot climate and limited roof insulation

Example: UK Quality Framework CIGA for Insulation of Cavity Walls



Copyright <https://www.ciga.co.uk/>

- Cavity Insulation Guarantee Agency (CIGA)
- Established in 1995
- Provision of 25 years guarantee for cavity wall insulation fitted by registered installers in the UK
- Residential and non-residential buildings
- List of system designers and installers
- Guarantee covers defects in material + workmanship
- Since 2013 „hard to treat“ cavity insulation guarantee for homes with > 3 storeys or walls with narrow cavities
- CIGA HTT Guarantee was issued for nearly 130000 home owners within 2013

© Fraunhofer IBP

